



Murrami Quarry Pollution Incident Response Management Plan v3 ENV-PLA-2211 MURQ-011

Environment Protection Licence Number: 2674



Murrami Quarry Contour Road, Murrami, NSW

	Title	Name	Date
Creator	Principal Environmental Scientist	B Dwyer	27/03/2023
Reviewer	Regional Quarry Manager – Milbrae West	T Walter	27/03/2023
Reviewer / Approver	Environment and Compliance Manager	S Rankin	28/03/2023





Contents

1	Purpose	3
2	Definition of Material Harm to the Environment	3
3	Environment Protection Licence (EPL) Details	4
4	Pollution Incident – Person/s Responsible	5
5	Notifications – Relevant Authorities	5
6	Notifications – Neighbours and the Local Community [REDACTED]	6
7	Hazards - Description and Likelihood	7
8	Pollutants	9
9	Safety Equipment	9
10	Communicating with Neighbours and the Local Community	9
11	Maps and Site Plans	
12	Incident Response	13
13	Coordinating with Persons	16
14	Training	16
15	Testing and Updating the PIRMP	16
16	Document History	16
	re 1: Mawsons risk matrixre 2: Location of quarry and potentially impacted area	
	re 3: Location of potentially impacted neighbours proximate to the quarry	
	re 4: Location of pollutants, safety equipment and watercourses	
Tab	le 1: Potentially impacted neighbours proximate to Murrami Quarry [REDACTED]	6
Tab	le 2: Murrami Quarry risk assessment	7

1 Purpose

E.B. Mawson & Sons Pty Ltd holds an Environment Protection Licence with the NSW Environment Protection Authority (EPA) for the Milbrae Murrami Quarry. As per the *Protection of the Environment Operations Act 1997* (the POEO Act), the holder of an Environment Protection Licence must prepare, keep, test and implement a pollution incident response management plan (PIRMP) that complies with Part 5.7A of the POEO Act in relation to the activity to which the licence relates.

If a pollution incident occurs in the course of an activity so that material harm to the environment (within the meaning of section 147 of the POEO Act) is caused or threatened, the person carrying out the activity must **immediately** implement this plan in relation to the activity required by Part 5.7A of the POEO Act.

A copy of this plan must be kept at the licensed premises, or where the activity takes place in the case of mobile plant licences, and be made available on request by an authorised EPA officer and to any person who is responsible for implementing this plan.

Parts of the plan must also be available either on a publicly accessible website, or if there is no such website, by providing a copy of the plan to any person who makes a written request. The sections of the plan that are required to be publicly available are set out in section 74 of the Protection of the Environment Operations (General) Regulation 2022.

2 Definition of Material Harm to the Environment

This plan must be activated in the event of a *pollution incident* that causes or threatens *material harm* to the environment.

Pollution incident means a leak, spill or other escape or deposit of a substance, which causes or is likely to cause pollution (does not include an incident involving only the emission of noise).

Pollution means (broadly) release or introduction of any substance to air, land or water.

Material harm means actual *or potential* harm to health or safety of human beings or ecosystems that is not trivial, cost to make good exceeds \$10,000. Includes incidents that only impact the premises where the incident occurs.









Environment Protection Licence (EPL) Details

E.B. Mawson & Sons Proprietary Limited Name of licensee:

ABN: 14 004 519 617

EPL number: 2674

Milbrae Murrami Quarry

Premises name and address: Contour Road

MURRAMI NSW 2705

Name: Tom Walter

Company or business contact details (business hours):

Position or title: Quarry Manager

Business hours contact number: 0408 411 059

Email: enquiries@mawsons.com.au

Name: Shari Rankin

Company or business contact details (after hours):

Position or title: Environment and Compliance Manager

Business hours contact number: 0433 845 432

Email: srankin@mawsons.com.au

Environmental concerns or complaints

Business hours contact number: 1800 423 456

After hours contact number: 0433 845 432

Website address: www.mawsons.com.au

Scheduled activity/activities

on EPL:

Extractive activities

Fee-based activity/activities

on EPL:

Extractive activities

Ancillary activities on EPL:

N/A







4 Pollution Incident - Person/s Responsible

Responsibility	Person Responsible
	Name: Tom Walter
	Position or title: Quarry Manager
PIRMP activation	Business hours contact number: 0408 411 059
	After hours contact number/s: 0408 411 059
	Email: twalter@mawsons.com.au
	Name: Shari Rankin
Notifying relevant authorities	Position or title: Environment & Compliance Manager
Notification should be made by a person with an appropriate	Business hours contact number/s: 0433 845 432
level of authority within the	After hours contact number/s: 0433 845 432
company.	Email: srankin@mawsons.com.au
	Name: Tom Walter
	Position or title: Quarry Manager
Managing response to pollution incident	Business hours contact number: 0408 411 059
polition incluent	After hours contact number/s: 0408 411 059
	Email: twalter@mawsons.com.au

5 Notifications - Relevant Authorities

Incidents that cause or threaten material harm (actual or potential harm that is not trivial, eg. loss/damage ~ \$10,000) must be reported to **all** relevant authorities **immediately**.

Authority	Contact Number
Fire and Rescue NSW / Rural Fire Service (first notification)	000
EPA	131 555
NSW Health – Murrumbidgee Public Health Unit	1800 011 824
SafeWork NSW	131 050
Local authority – Leeton Shire	02 6953 0911
NSW Resources Regulator	1300 814 609







Notifications – Neighbours and the Local Community [REDACTED]

Neighbours potentially impacted by a pollution incident at Murrami Quarry are those listed in Table 1 that are within approximately 2km of the quarry (see Figure 2 in Section 11). Contact details in Table 1 for neighbours proximate to Murrami Quarry have been redacted for privacy reasons.

Notification of neighbours is the responsibility of the Quarry Manager but may be delegated to a suitably trained person at the discretion of the Quarry Manager and in consultation with the Environment and Compliance Manager. It is the responsibility of the Quarry Manager to inform and update the Environment and Compliance Manager and to record the incident in O4i in accordance with ENV-PRO-001 Environmental Incident Management Procedure.

Table 1: Potentially impacted neighbours proximate to Murrami Quarry [REDACTED]

Neighbour Number	Address	Lot Number(s)	Contact Name(s)	Contact Details	Communication Requirements
			DEDACTED	•	

ENV-PLA-2211 MURQ-011 v3 Page 6 of 16



7 Hazards - Description and Likelihood

Table 2: Murrami Quarry risk assessment

		Risk Asse	essment Prior to Actions	Pre-emptive		Risk Ass	sessment After P Actions	re-emptive	Monitoring	and Continuous Improvement	
Hazard	Pollution Incident (Material Harm)	Inherent Risk			Pre-emptive Actions		Residual Risk				
	(Material Harri)			Risk Rating		Likelihood	Consequence	Risk Rating	Aspect to be Monitored	Details of Monitoring and Continuous Improvement	
Dust	Excessive dust resulting in nuisance to neighbours	Likely	Minor	Medium	Compliance with approved operating hours Exposed/disturbed areas minimised and revegetation undertaken progressively to reduce exposed/disturbed areas	Unlikely	Minor	Low		 Monitoring to be conducted in accordance with EPL 2674 and ENV-PLA-001 Air Quality Management Plan Monitoring as part of environmental inspections (as per ENV-PRO-002 Environmental Risk Management Procedure) as well as opportunistic site visits Community interactions (including complaints) to be recorded and reported where appropriate 	
Dust	Excessive dust resulting in health impacts to neighbours	Possible	Major	High	 Water sprays installed and operational at critical locations on processing plant Drill rig fitted with engineered dust extraction/suppression 	Rare	Moderate	Medium	Air quality as per EPL 2674 and ENV-PLA-		
Dust	Excessive dust resulting in biodiversity impacts	Possible	Minor	Medium	 Water cart utilised on exposed areas, roads and hardstands Site access roads and haul roads adequately maintained and appropriately speed limited Dust generating plant shut down during dust amplifying weather conditions Material drop heights for stockpiles reduced Continuous dust monitor deployed 	Unlikely	Minor	Low	001 Air Quality Management Plan		
Surface Water	Unauthorised discharge of wastewater resulting in ecosystem damage to receiving waterway	Possible	Moderate	Medium	 Access and haul roads designed with sufficient diversion drains and culverts to ensure stormwater is diverted away from receiving waterways Access and haul roads graded and orientated to slow the flow of stormwater 	Unlikely	Minor	Low	Water quality as per	 Monitoring to be conducted in accordance with EPL 2674 and ENV-PLA-2211 MURQ-005 Murrami Quarry Surface Water and Groundwater Management Plan Monitoring as part of environmental inspections (as per ENV-PRO-002 Environmental Risk Management Procedure) as well as opportunistic 	
Surface Water	Localised flooding as a result of quarry impacts on surface water systems resulting in impacts to neighbours	Possible	Moderate	Medium	 Stormwater directed to sumps Surface water drainage line/waterway kept free of debris and diversion structures employed to direct stormwater away from them Erosion and sediment control structures 	Unlikely	Minor	Low	EPL 2674 and ENV- PLA-2211 MURQ-005 Murrami Quarry Surface Water and Groundwater Management Plan		
Surface Water	Sedimentation resulting in ecosystem damage to receiving waterway	Possible	Minor	Medium	employed to prevent the sedimentation of receiving waterway Exposed/disturbed areas minimised and revegetation undertaken progressively to reduce exposed/disturbed areas	Unlikely	Minor	Low		site visits	
Groundwater	Groundwater contamination resulting in aquifer pollution	Possible	Major	High	 Hydrocarbons stored in appropriately bunded areas (as per Figure 4) Adequate spill kits are available on site and training is provided in their use Storage of hydrocarbons is audited during environmental inspections and opportunistic site visits 	Rare	Moderate	Medium	Water quality as per EPL 2674 and ENV- PLA-2211 MURQ-005 Murrami Quarry Surface Water and Groundwater Management Plan	Monitoring to be conducted in accordance with EPL 2674 and ENV-PLA-2211 MURQ-005 Murrami Quarry Surface Water and Groundwater Management Plan Monitoring as part of environmental inspections (as per ENV-PRO-002 Environmental Risk Management Procedure) as well as opportunistic site visits	
Fire	Uncontrolled fire started or exacerbated as a result of quarry activities resulting in impacts to neighbours	Possible	Major	High	 Plant and equipment is well maintained and fitted with spark arrestors and fire extinguishers No "hot works" undertaken on days of Total Fire Ban without written approval of RFS Liaison with RFS undertaken in times of extreme fire danger Refuelling and servicing conducted is designated areas 	Rare	Moderate	Medium	 Emergency warnings Extreme weather Total Fire Ban days 	Environmental inspections (as per ENV-PRO-002 Environmental Risk Management Procedure) as well as opportunistic site visits	

ENV-PLA-2211 MURQ-011 v3





	Pollution Incident	Risk Asse	essment Prior to Actions	Pre-emptive		Risk Ass	sessment After P Actions	re-emptive	Monitoring	and Continuous Improvement
Hazard	(Material Harm)		Inherent Risk		Pre-emptive Actions		Residual Risk			
		Likelihood	Consequence	Risk Rating		Likelihood	Consequence	Risk Rating	Aspect to be Monitored	Details of Monitoring and Continuous Improvement
					Quarry activities undertaken in accordance with ENV-PLA-2211 MURQ-002 Murrami Quarry Fire Management Plan					
Fuels, Lubricants and Other Hazardous Materials	Spill resulting in ecosystem damage to receiving waterway	Possible	Moderate	Medium	 Storage and handling of hydrocarbons is in accordance with AS 1940 and the Dangerous Goods Act 1975 Hydrocarbons stored in appropriately bunded areas (as per Figure 4) Adequate spill kits are available on site and training is provided in their use 	Unlikely	Minor	Low	Water quality as per EPL 2674 and ENV- PLA-2211 MURQ-005 Murrami Quarry Surface Water and Groundwater Management Plan	Monitoring to be conducted in accordance with EPL 2674 and ENV-PLA-2211 MURQ-005 Murrami Quarry Surface Water and Groundwater Management Plan Monitoring as part of environmental inspections (as per ENV-PRO-002 Environmental Risk Management Procedure) as well as opportunistic site visits
Fuels, Lubricants and Other Hazardous Materials	Spill resulting in terrestrial ecosystem damage	Possible	Moderate	Medium	 Storage of hydrocarbons is audited during environmental inspections and opportunistic site visits 	Unlikely	Minor	Low	Area around hydrocarbon storages	Monitoring as part of environmental inspections (as per ENV-PRO-002 Environmental Risk Management Procedure) as well as opportunistic site visits
Pests, Weeds and Diseases	Infestation/outbreak resulting in ecosystem damage	Possible	Moderate	Medium	Pest plants and animals, and diseases managed in accordance with ENV-PLA-2211 MURQ-003 Murrami Quarry Pest and Weed Management Plan Appropriately licensed personnel engaged to undertake pest plant and animal control Control of pest plant and animals, and diseases audited during environmental inspections and opportunistic site visits	Unlikely	Minor	Low	Presence and control of pest plants and animals, and diseases as per ENV-PLA-2211 MURQ-003 Murrami Quarry Pest and Weed Management Plan	Monitoring of presence and control of pest plants and animals, and diseases as per ENV-PLA-2211 MURQ-003 Murrami Quarry Pest and Weed Management Plan Monitoring as part of environmental inspections (as per ENV-PRO-002 Environmental Risk Management Procedure) as well as opportunistic site visits

This risk assessment has been conducted utilising the following matrix.

Consequence										
		Insignificant	Minor	Moderate	Major	Critical				
	Rare	Low	Low	Medium	Medium	High				
=	Unlikely	Low	Low	Medium	High	High				
Likelihood	Possible	Low	Medium	Medium	High	Very High				
8	Likely	Medium	Medium	High	Very High	Very High				
	Almost Certain	Medium	High	Very High	Very High	Very High				

Figure 1: Mawsons risk matrix

ENV-PLA-2211 MURQ-011 v3 Page 8 of 16



8 Pollutants

Figure 4 in Section 11 provides the locations of pollutants described in the table below.

Location/tank	Pollutant	Maximum Volume
Overhead tank on western side of quarry	Diesel fuel	4,000L

9 Safety Equipment

Figure 4 in Section 11 provides the locations of safety equipment described in the table below.

Equipment	Location
Fire extinguishers	In all buildings, on mobile equipment and in light vehicles
Spill kit	Adjacent to diesel tank
Personal Protective Equipment (PPE)	Provided and required to be used in accordance with WHS-PRO-017 Personal Protective Equipment (PPE) Procedure
First aid kits	In site office

10 Communicating with Neighbours and the Local Community

Each neighbour within 2km of the quarry will receive an in-person visit from Mawsons/Milbrae staff and a copy of this PIRMP with explanation of contact details for notifying Mawsons/Milbrae of complaints or concerns.

Specific messages in the event of a material pollution incident:

- Dust persons in the affected area should close windows and doors and remain inside until advised otherwise by Mawsons/Milbrae or emergency services.
- Fire implement fire safety plan and follow advice of emergency services
- Spill to waterways avoid entering or fishing in downstream waterways
- Pests, weeds and disease type of pest, weed or disease, location of outbreak, maintain vigilance

Minimising harm to persons on the premises

- Evacuate and assemble at the evacuation point at the front entry gate
- Initiate notifications, including emergency services
- Activate the emergency response plan





11 Maps and Site Plans




Figure 2: Location of quarry and potentially impacted area

ENV-PLA-2211 MURQ-011 v3 Page 10 of 16








Figure 3: Location of potentially impacted neighbours proximate to the quarry

ENV-PLA-2211 MURQ-011 v3 Page 11 of 16








Figure 4: Location of pollutants, safety equipment and watercourses

ENV-PLA-2211 MURQ-011 v3 Page 12 of 16



12 Incident Response

Actions to be taken during or immediately after a pollution incident and the person responsible.

Note: Actions should only be taken if safe to do so.

			Immediate Response	Early V	Varning	Mitigatio	n Actions	Communica	tion Updates	Clea	ın Up	Close	e Out
			Quarry Manager	Quarry Manager	Environment and Compliance Manager	Quarry Manager	Environment and Compliance Manager	Quarry Manager	Environment and Compliance Manager	Quarry Manager	Environment and Compliance Manager	Quarry Manager	Environment and Compliance Manager
	Dust	Excessive dust resulting in nuisance to neighbours	Shut down dust generating plant and/or equipment	Text message to neighbours	Notify EPA	Identify source of excessive dust generation Activate dust suppression if not already active Redirect water cart to most heavily affected area	Review weather data Assess clean up obligations	Text message to neighbours	Update EPA	As directed by Environment and Compliance Manager	Liaise with Quarry Manager to ensure clean up meets obligations	 Text message to neighbours Report incident in O4i Provide information for investigation 	 Conduct investigation Provide report to EPA
Incident (Material Harm)	Dust	Excessive dust resulting in health impacts to neighbours	Shut down dust generating plant and/or equipment	Phone call to neighbours	Notify EPA	Identify source of excessive dust generation Activate dust suppression if not already active Redirect water cart to most heavily affected area	Identify area of impact Assess clean up obligations Engage WHS team Engage other regulators and/or agencies as required	Phone call to neighbours	Update EPA	Engage contractor to clean exteriors of impacted residences and rainwater tanks, re-fill tanks	Liaise with contractor to ensure clean up meets obligations	 Phone call to neighbours Report incident in O4i Provide information for investigation 	Conduct investigation Provide report to EPA
	Dust	Excessive dust resulting in biodiversity impacts	Shut down dust generating plant and/or equipment	250	Notify EPA	Identify source of excessive dust generation Activate dust suppression if not already active Redirect water cart to most heavily affected area	Review weather data Assess clean up obligations		Update EPA	As directed by Environment and Compliance Manager	Liaise with Quarry Manager to ensure clean up meets obligations	 Report incident in O4i Provide information for investigation 	Conduct investigation Provide report to EPA

ENV-PLA-2211 MURQ-011 v3 Page 13 of 16





		Immediate Response	Immediate Early Warning		Mitigatio	n Actions	Actions Communication Updates			ın Up	Close Out	
		Quarry Manager	Quarry Manager	Environment and Compliance Manager	Quarry Manager	Environment and Compliance Manager	Quarry Manager	Environment and Compliance Manager	Quarry Manager	Environment and Compliance Manager	Quarry Manager	Environment and Compliance Manager
Surface Water	Unauthorised discharge of wastewater resulting in ecosystem damage to receiving waterway	Divert water to sump or away from sensitive receiving environment		Notify EPA	Collect water samples for analysis	Assess clean up obligations		Update EPA	As directed by Environment and Compliance Manager	Liaise with Quarry Manager to ensure clean up meets obligations	Report incident in O4i Provide information for investigation	Conduct investigation Provide report to EPA
Surface Water	Localised flooding as a result of quarry impacts on surface water systems resulting in impacts to neighbours	Divert water to sump or away from sensitive receiving environment	Phone call to neighbours	Notify EPA	Collect water samples for analysis	Engage WHS team Engage other regulators and/or agencies as required Assess clean up obligations Review weather data	Phone call to neighbours	Update EPA	As directed by Environment and Compliance Manager	Liaise with Quarry Manager to ensure clean up meets obligations	Phone call to neighbours Report incident in O4i Provide information for investigation	Conduct investigation Provide report to EPA
Surface Water	Sedimentation resulting in ecosystem damage to receiving waterway	Divert water to sump or away from sensitive receiving environment		Notify EPA	Install sediment control devices Collect water samples for analysis	Assess clean up obligations		Update EPA	As directed by Environment and Compliance Manager	Liaise with Quarry Manager to ensure clean up meets obligations	Report incident in O4i Provide information for investigation	Conduct investigation Provide report to EPA
Groundwater	Groundwater contamination resulting in aquifer pollution	Divert contamination source to sump or away from sensitive receiving environment			Collect water samples for analysis	Assess clean up obligations		Update EPA	As directed by Environment and Compliance Manager	Liaise with Quarry Manager to ensure clean up meets obligations	 Report incident in O4i Provide information for investigation 	Conduct investigation Provide report to EPA
Fire	Uncontrolled fire started or exacerbated as a result of quarry activities resulting in impacts to neighbours	Call 000Stop WorkClose Site	Phone call to neighbours		Activate ENV- PLA-2211 MURQ-002 Murrami Quarry Bushfire Management Plan	Engage WHS team Engage other regulators and/or agencies as required	Phone call to neighbours		As directed by Environment and Compliance Manager	Assess clean up obligations Liaise with Quarry Manager to ensure clean up meets obligations	 Phone call to neighbours Report incident in O4i Provide information for investigation 	Support WHS team to conduct investigation
Fuels, Lubricants and Other Hazardous Materials	Hydrocarbon spill resulting in ecosystem damage to receiving waterway	Stop spill at the source		Notify EPA	Collect water samples for analysis	Assess clean up obligations		Update EPA	As directed by Environment and Compliance Manager	 Assess clean up obligations Liaise with Quarry Manager to ensure clean up meets obligations 	Report incident in O4i Provide information for investigation	Conduct investigation Provide report to EPA

ENV-PLA-2211 MURQ-011 v3





			Immediate Response	Early Warning		Mitigation Actions		Communication Updates		Clean Up		Close Out	
			Quarry Manager	Quarry Manager	Environment and Compliance Manager	Quarry Manager	Environment and Compliance Manager	Quarry Manager	Environment and Compliance Manager	Quarry Manager	Environment and Compliance Manager	Quarry Manager	Environment and Compliance Manager
_	Fuels, Lubricants and Other Hazardous Materials	Hydrocarbon spill resulting in terrestrial ecosystem damage	Stop spill at the source		Notify EPA	Collect soil samples for analysis	Assess clean up obligations		Update EPA	As directed by Environment and Compliance Manager	Assess clean up obligations Liaise with Quarry Manager to ensure clean up meets obligations	 Report incident in O4i Provide information for investigation 	 Conduct investigation Provide report to EPA
	Pests, Weeds and Diseases	Pest plant or animal infestation or disease outbreak resulting in ecosystem damage	Control traffic movements to prevent spread	Text message to neighbours	Notify Local Land Services (LLS)	Assess the extent or spread of the infestation or outbreak	Engage LLS for advice and develop a containment plan Engage other regulators and/or agencies as required	Text message to neighbours	Update LLS	Engage suitably qualified contractor to conduct control or eradication works	Liaise with contractor to ensure clean up meets obligations	 Report incident in O4i Provide information for investigation 	 Conduct investigation Provide report to LLS

ENV-PLA-2211 MURQ-011 v3 Page 15 of 16



13 Coordinating with Persons

Initial notifications and status updates to neighbours will be undertaken by the Quarry Manager or their delegate as described in Section 6.

Initial notifications to regulatory authorities will be undertaken by the Environment and Compliance Manager or their delegate.

Coordination with regulatory authorities and emergency responders that attend site will be managed by the Quarry Manager or their delegate.

Status updates to, regulatory authorities, and emergency responders that are not on site will be managed by the Environment and Compliance Manager or their delegate.

14 Training

Nature of Training	Training Objectives				
Site Induction	Ensure that all personnel entering the site are aware of the hazards and control measures and any specific site conditions within the quarry				
Emergency Response	During the testing of this PRIMP workers will have the opportunity to be trained on the emergency response equipment such as spill kit contents and use of these items. Formal fire extinguisher training.				

15 Testing and Updating the PIRMP

It is a legal requirement to test the plan every 12 months and within one month of any pollution incident that caused or threatened material harm to the environment.

The PIRMP testing form is hosted on the Mawsons intranet at https://mawsons.integralcs.com/inform/manageinformformrecord/subpageadd/form_id/300. Actions and updates to the PIRMP are also managed through the Mawsons intranet.

16 Document History

Version	Date	Amended By	Reason for Change
1			Document created
2	01/05/2021		
3	27/03/2023	B Dwyer	Updated following change of site ownership